

Operating Instructions

AS pro



PEWA
Messtechnik GmbH

Weidenweg 21
58239 Schwerte

Tel.: 02304-96109-0
Fax: 02304-96109-88
E-Mail: info@pewa.de
Homepage: www.pewa.de



PRINTING ACTUALITY

Advanced technology and the high quality of our devices are ensured by continuous improvement. As a result, the specifications and information in this manual are subject to change without notice and may vary from the actual functions of your device. Errors and omissions excepted. All information, graphics and descriptions in this document without guarantee. Specifications are subject to change without further notice.

ONE-YEAR LIMITED WARRANTY

Warranty Duration: The device described herein is warranted to the original purchaser for a period of one (1) year from the original purchase date. **Warranty Coverage:** This device is warranted against defective materials or workmanship which may appear within the one year warranty period. **Warranty Performance:** During the above one-year warranty period, a defective device will either be repaired or replaced with a reconditioned model (at our option) when the product is returned, postage prepaid, to the ibb facility. **Warranty Disclaimer:** The manufacturer makes no other warranty whatsoever, express or implied, including, without limitation, any implied warranties of merchantability or fitness for a particular purpose. The manufacturer shall not be liable for loss of use of the device or any other incidental or consequential costs, expenses, or damages incurred by the user. This warranty is void if the product has been opened or damaged by accident, unreasonable use, neglect, improper service, or other causes not arising out of defects in material or workmanship.

COPYRIGHT NOTICE

© 2008 by ibb Ingenieurbüro Becker GmbH, Oer-Erkenschwick, Germany.
No one is permitted to reproduce or duplicate, in any form, the whole or part of this manual without written permission from the manufacturer.
Printed in Germany.

TABLE OF CONTENTS

1	PRODUCT DESCRIPTION	5
1.1	ADEQUATE USE	5
1.2	DESIGN	6
1.3	FUNCTIONAL DESCRIPTION	7
1.3.1	General	7
1.3.2	Measurement Procedures	7
1.4	SPECIFICATIONS	8
1.5	EC DECLARATION OF CONFORMITY	9
2	SAFETY INFORMATION	10
2.1	GENERAL	10
2.2	CHARGING INSTRUCTIONS	10
3	OPERATION	11
3.1	POWER ON/OFF/ DISPLAY / FEATURES / FUNCTION KEYS	11
3.1.1	Powering the Device On And Off	11
3.1.2	Display	11
3.1.3	Arrow Keys	12
3.1.4	Function Keys	12
3.1.5	Memory Management Information	12
3.1.6	Selecting the desired RFID transponder type (optional)	13
3.1.7	Selecting the required storage method	14
3.2	MEASURING	15
3.2.1	Starting Measurements	15
3.2.2	Special Feature for Recording Series of Measurements	20
3.2.3	Completing a Series of Measurements	21
3.3	DISPLAYING AND PRINTING STORED SERIES OF MEASUREMENTS	23
3.3.1	Displaying Series of Measurements	24
3.3.2	Printing Series of Measurements	26
3.3.3	Special Printing Features	27
3.3.4	Printing Example	27
3.4	DELETING MEASUREMENTS	28
3.5	USING THE BATTERY CHARGER	29
3.5.1	State of Charge Display	29
3.5.2	Charging Procedure	29

4	TROUBLESHOOTING	30
4.1	VOLTAGE MEASUREMENT PROBLEMS.....	30
4.2	PROBLEMS WITH THE OPERATING TIME/POWERING-ON	31
4.3	PRINTING PROBLEMS	31
4.4	PROBLEMS WITH THE INFRARED CONNECTION TO THE PC.....	32
4.5	TROUBLESHOOTING PROBLEMS WHEN READING RFID TRANSPONDER DATA	32
5	MAINTENANCE	33
5.1	CLEANING	33
5.2	MAINTENANCE	33
6	ACCESSORIES AND REPLACEMENT PARTS	34
6.1	ACCESSORIES	34
6.2	REPLACEMENT PARTS	35

1 Product Description

1.1 Adequate Use

Please follow the instructions given in this document to prevent damage or fatal injury when using the AS pro:

- This device may only be used according to its proper use for which it is designed. Do not use the device for any other purposes.
- Read the operating instructions carefully before powering on and using this device.
- Also read the "Safety Information" chapter thoroughly before using this device.


The AS pro is exclusively designed for measuring, storing and displaying direct voltages.

An adequate use implies that you read this manual and observe all the instructions contained herein, especially the safety information. Furthermore, any adequate use implies that all maintenance work will be performed within the specified intervals.

Safe operation cannot be guaranteed if the AS pro is not used according to this instructions.

The producer shall not be liable for any personal injury or material damage arising from improper use of this device.

1.2 Design



1.3 Functional Description

1.3.1 General

State-of-the-art storage battery and power supply technology is impossible without reliable, easy-to-use and highly accurate devices which monitor the battery's state of charge and operation. Professional users are looking for the following requirements:

Accurate measurements, series of measurements which can be recorded and stored, output options to external computer systems, operation which is independent of the mains, rugged design and reliable technology even in unfavorable environmental conditions. Our answer to all these requirements is just as clear - AS pro. The AS pro is a mobile measuring system especially designed for industrial applications and provides outstanding functionality and high suitability for everyday use.

The AS pro is a portable measuring instrument designed for recording, displaying and storing a storage battery's or accumulator's voltage (cell voltage, block voltage or total voltage). A built-in signal generator beeps each time a measurement is stored. Optionally, a headphone can be connected.

The AS pro is operated using a tactile keypad and a graphics display. Current measurements and stored measurements as well as the average, minimum and maximum value can also be determined. By means of manual input, a battery temperature can also be assigned to a series of measurements. All of the information on a measured series can be transmitted to a PC or notebook via an infrared interface. This data can then be edited and processed further (e.g. printed, evaluated and converted into graphics in MS Excel).

The AS pro can be equipped with an optional bar-code reader which is used to assign battery/storage cell identification numbers (ID numbers) to the measured series in order to simplify data management.

The AS pro is powered by an integrated NiMH accumulator which can be recharged with the battery charger supplied. After a full charge this accumulator operates for up to 20 hours and can generally be used in the service field for about 5 days.

1.3.2 Measurement Procedures

The AS pro provides two different procedures for measuring voltages:

- Single method (only once), i.e. after applying the measuring tips to the voltage to be measured, the measured value is being stored automatically.
- Single method (only once), i.e. after applying the measuring tips to the voltage to be measured, the measured value is being stored only after a manual button has been pressed.
- Cyclic method, i.e. the value of a continuously applied voltage is being saved in a specified time interval.

After a series of measurements is complete, all saved values can be displayed on the AS pro, printed or transmitted to a PC.

1.4 Specifications

- Measuring range: 0-20V and 0-600V DC
- Resolutions: 0.01V at 20V; 0.1V at 600V measuring range
- Measuring accuracy: 0.05% of the measuring range ± 1 digit
- Power supply: internal NiMH accumulators
- Operating time: approx. 20 hours after full charge
- State of charge indicator resolution: 10%
- The accumulators are charged by an external battery charger via a charge jack
- Charging time: approx. 3 hours
- Automatic switchover to float charging
- Current and stored measurements are displayed on a liquid crystal graphics display (LCD)
- Measured values can be stored together with date, time, and cell number
- Acoustic signal when a measurement is stored
- Storage and display of a measurement series identification
- Identification input via keyboard or optional RFID transponder 125 kHz
Type of transponder: UNIQUE, HITAG1, HITAG2
- Infrared interface for transmission of stored values to a PC or notebook
- Infrared interface for stored value transmission to an external printer
- Allowable distance to infrared receiver (direct line-of-sight) ≤ 60 cm
- Calibration interval: biannual calibration for service use;
annual calibration for laboratory use
- Temperature for guaranteed accuracy: $+23^{\circ}\text{C} \pm 5^{\circ}\text{C}$
- Operating temperature: $+10^{\circ}\text{C}$ to $+40^{\circ}\text{C}$ / maximum 80% relative humidity (noncondensing)
- Storage temperature: 0°C to $+50^{\circ}\text{C}$ / maximum 80% relative humidity (noncondensing)
- IP44 protection system
- Dimensions (LxWxH): 185x92x35 mm
- Weight: 350 g

1.5 EC Declaration of Conformity

**EC Declaration of Conformity
according to EMC directive (2004/108//EG)
according to low voltage directive (2006/95/EG)**

The manufacturer/distributor

ibb Ing.-Büro Becker GmbH
Winkelfeld 9-11
45739 Oer-Erkenschwick, Germany

hereby confirms that the following product

Product designation:	AS pro
Serial designation / type designation:	00963-0000.xx
Manufacturing year:	as of 05.2008

meets the requirements and regulations of the above EEC directives.

The following harmonized standards have been applied:

- EN 61000-6-3:2007 Electromagnetic compatibility (EMC); Generic emission standard; Residential, commercial and light industry
- EN 61000-6-2:2005 Electromagnetic compatibility (EMC); Generic immunity standard; Industrial environment
- EN 61010-1:2001 Safety requirements for electrical equipment for measurement, control and laboratory use; Part 1: General requirements



Oer-Erkenschwick, 06.05.2008

Bernd Scherbeck, Director

2 Safety Information

2.1 General



Read this safety information carefully before using the device!

The **AS pro** was designed and produced in accordance with harmonized standards and other technological specifications. This device therefore complies to state-of-the-art technology and provides maximum safety.

However, in everyday use this level of safety can only be met if all of the appropriate measures are taken. The operator/user of the **AS pro** is responsible for planning, implementing and controlling these measures.

Especially, the user must ensure that:

- the device will be used properly and adequately (see "Product Description" chapter)
- the device and its accessories (measuring leads, battery charger, etc.) will be operated only if they are failure-free and fully functional
- the complete and legible instruction manual is stored with the device at the place of operation
- the device is operated, maintained and repaired by authorized and experienced personnel only
- the staff responsible for this device is trained in all matters of occupational safety and environmental protection and also is familiar with this operating manual and the safety information contained herein
- all safety labels and warnings will be maintained in a legible state and no safety labels and warnings attached to the device will be removed

2.2 Charging Instructions

- Only use the supplied battery charger for charging the internal NiMH accumulators.
- Do not charge the storage batteries at temperatures above 35°C.
- The **AS pro** must be powered off during charging so that the battery charger can identify fully charged storage batteries.
- Please read the chapter "Using the Battery Charger" carefully.

3 Operation


3.1 Power on/off/ Display / Features / Function Keys

3.1.1 Powering the Device On And Off


Press the [ENTER] key for at least one second to power the AS pro on.
 By pressing the F9 key ([SHIFT]+[9]), you will power the AS pro off. If Auto Power Off is enabled, the device will switch off after a set period of inactivity (see AS pro Settings).

3.1.2 Display

If you power the AS pro on by pressing [ENTER], the following text will be displayed:



In the bottom line you will see the AS pro version number. Below that, the device displays:



3.1.3 Arrow Keys

The [↑] and [↓] arrow keys are used to select different features which then are confirmed by pressing [ENTER].

The [←] and [→] arrow keys are used for changing and applying the features of a selected function.

By pressing [CLEAR] you can delete input which has not yet been confirmed by pressing [ENTER]. If there is no input, the device will display the previous menu item.

3.1.4 Function Keys

All of the key functions on the keypad labeled in blue can be selected by simultaneously pressing [SHIFT] + [1 ... 9] and so on (the desired function key).

- F1 displays the AS pro function key layout
- F2 battery voltage
- F3 enables/disables the display of date and time
- F4 decreases the display contrast
- F5 enables the "Auto" measuring range (automatic range switching 600V/20V)
- F6 informs about memory management and available/used series of measurements/measured values
- F7 increases the display contrast
- F8 sets the measuring range to 600V
- F9 powers the AS pro off

The function keys F1 to F9 can be selected and used from any menu item.

3.1.5 Memory Management Information

The AS pro can store up to 200 series of measurements and a total of 20,000 measured values.

If you press the function key F6, the series of measurements and measured values will be displayed on the AS pro's LCD:

```
TEST SERIES      VALUE
IDLE / BUSY      IDLE / BUSY
198 / 002        19960 / 00040
VER: 1.51 13.03.2008
                ->A Enter
```

The above example illustrates that the AS pro has stored 2 series of measurements with a total of 40 measured values. By pressing [ENTER] you will return to the previous screen.

3.1.6 Selecting the desired RFID transponder type (optional)

AS pro is able to read 3 different types of RFID transponders. Select the required transponder type by using the Toolkit Software, the data management software, or via the information menu by pressing the F6 key. If the AS pro is provided with a reader for RFID transponders, the information menu will display the following:

```

TEST SERIES      VALUE
IDLE / BUSY     IDLE / BUSY
 198 / 002      19960 / 00040
VER: 1.51 13.03.2008
↑↓ RFID UNIQUE  ->A Enter

```

This means that the “UNIQUE” RFID transponder type is set in the AS pro. Use the [↑] and [↓] keys to select another transponder type.

RFID UNIQUE	RFID transponder, reads the UID as an identification number
RFID HITAG1	RFID transponder, reads the identification number of up to 20 digits
RFID HITAG2	RFID transponder, reads the identification number of up to 16 digits

Explanation:

The “UNIQUE” RFID transponder type has stored a unique serial number only, which is the Unique Identification Number (UID). This invariable number was entered by the manufacturer and cannot be modified.

For “HITAG1” or “HITAG2” transponder types it is possible to enter customer-specific data into the transponder. This is done by using the AS pro data management software in conjunction with a reader/writer for RFID transponders (please refer to the AS pro data management user manual).

Various types of RFID transponders:



3.1.7 Selecting the required storage method

The storage method can be selected either by using the Toolkit software, the data management software, or directly at the AS pro. Press the F6 key to open the information menu and select the required option.

```
TEST SERIES      VALUE
IDLE / BUSY      IDLE / BUSY
 198 / 002       19960 / 00040
VER: 1.51 13.03.2008
↑↓ RFID UNIQUE  ->A Enter
```

↑

This means that the AS pro is in automatic storage mode.
Use the [→] key to select another storage method:

->A automatic storage
->T manual storage after pressing a manual button

Explanation:

- Cyclic storage can only be selected when starting a series of measurements. In this mode, the manual button is disabled (does not have any function).
- Switching between storage methods [A/T] can also be done during a series of measurements.
- Parameters for automatic storage can only be modified in the Toolkit software or in the data management software.

3.2 Measuring

Press the [ENTER] key to power on the AS pro. You can immediately start measuring as with any usual voltmeter.

If you power the AS pro on by pressing [ENTER], the following text will be displayed:

```

113.8V
13.03.2008 13:49:55
F1      Enter
  
```

3.2.1 Starting Measurements


A series of measurements is a collection of related measurements (measured values) belonging to a battery array, to a system or to a measurement task. Press the [ENTER] key once again to select the main menu and start a series of measurements.

```

Start Data Logging
View Test Series
Delete Test Series
↑↓      Clear  Enter
  
```

The [↑] and [↓] arrow keys are used to select different features which then are confirmed by pressing [ENTER]. By pressing [CLEAR] you will return to the previous menu item.

You have selected `Start` measurements. Press [ENTER] to confirm your selection. The menu for starting a series of measurements is displayed.



The [↑] and [↓] arrow keys are used to select different features which then are confirmed by pressing [ENTER].

The [←] and [→] arrow keys are used for changing and applying the selected function. By pressing [CLEAR] you can return to the previous menu item.

An identification number (ID number) is a unique designation for a series of measurements. The identification number is used for identifying measurements so that this measurement can be assigned to a storage battery, power supply system or to a measurement task at a later time.

There are three different types of identification numbers:

- Ident No. Manual for entering the identification number via the device's keypad
- Ident No. RFID Reading the identification number via an RFID transponder reader (available only if the device is equipped with an RFID transponder reader):
- Ident No. w/o no identification number is being entered or read in

Storage Options:

- Store Mode Single manual voltage measurement
The voltage to be measured is measured individually and manually and then stored by the AS pro (see page 16).
- Store Mode Cyclic automatic voltage measurement in a range of between 1 second to 60 minutes and 59 seconds (This setting can only be applied by using the PC program.)
The voltage source to be measured is continuously connected to the AS pro. The AS pro will save the measurements cyclically in the set time interval. This measurement procedure is used for recording voltage curves.

Entering the identification number via keypad:

```

Start 001 rem. 20000
Enter Ident No.
XXXXXXXXXXXXXXXXXXXXX
↑↓↔    Clear   Enter
```

Enter the identification number manually on the device's keypad.
 Press the [↑] and [↓] arrow keys to gradually delete a number in the forward [↓] or backward direction [↑].
 Press the [←] or [→] arrow keys to gradually move the cursor back [←] and forth [→] within an input number and to make changes.
 Confirm your input by pressing [ENTER].
 Press [CLEAR] to return to the previous menu item.

Reading the identification number via an RFID transponder reader (available only if the device is equipped with an RFID transponder reader):

```
Start 001 rem. 20000
Read Ident No.
Read RFID HITAG2
->      <- Clear
```

Press [CLEAR] to move back to the previous menu item.

If the RFID transponder has been identified correctly, the **AS pro** will display:

```
Start 001 rem. 20000
Read Ident No.
Read RFID HITAG2
->RFID<- Clear
```

Reading the RFID transponder data will start immediately (please monitor the status indicator in the display's bottom right corner). After data transfer is complete, the device beeps and the **AS pro** stores the data as an identification number. Next (and also after you have entered the data via a keyboard), you can verify if the identification number is correct and read it in once again, if necessary.

```
Start 001 rem. 20000
Ident No. ok?
battery room 12
      Clear   Enter
```

Press [CLEAR] to move back to the previous menu item.
Press [ENTER] to confirm the input and to start measuring.

Please note:

To achieve optimum results when reading the RFID transponder data, the **AS pro** must be held in a distance of 1-3 cm in front of the RFID transponder for approximately 2 seconds, so that data transfer can start. The transponder coil is located beneath the black side of the casing's cover (see 1.2, **AS pro** design).



The RFID transponder must not be attached to a surface made of aluminum!

This example illustrates what is displayed when you start a series of measurements:

```
Start 001 rem. 20000
Ident No. Manual
Store Mode Single
↑↓      Clear   Enter
```

Pressing [ENTER] will start a series of measurements having the sequential number 001. The identification number will be entered manually, and the selected storage procedure is „single“. A remaining total of 20,000 measurements can be stored in the memory.

Pressing [CLEAR] will return you to the previous menu item without starting a measurement.

Press [ENTER] to start a series of measurements consisting of single measurements. First of all, the LCD will display:

```
⎓
Bat      0.00V
F1↑↓↔+  001  [ ] Enter
```

Now you can measure the total voltage of the storage battery („Bat“ instead of the cell number). Next, you can measure individual cell voltages. You can also skip the total voltage measurement by pressing the [ENTER] key.

```
⎓
001      2.35V
2.33V
F1↑↓↔+  001  [ ] Enter
```

Symbol for „single“ storage and display of the number of the next value that can be saved.

Display of the saved voltage (only if the value has already been saved). This measured value can be overwritten by a new measurement.

Number of the current series of measurements

The measurement is carried out by applying the measuring probes to the voltage to be measured. A short beep tone is emitted to confirm that the value has been saved. If the surrounding area is too noisy to hear the beep, you can connect the headphone.

Measurements will be saved according to the settings selected in the AS pro setup. If the option “manual button off” is selected, the measurement will be stored automatically. If the option “manual button on” is selected, the manual button on the measurement tip must be pressed in order to store the measured value. Depending on the AS pro settings, the device will emit different acoustic alarms if a limit value is exceeded or underrun.

If the limit value is exceeded, a short three-beep acoustic signal will sound; if the limit value is underrun, you hear a short two-beep signal. If the measured value is within the limit values, it beeps only once.

When you press [+], the current measurement will be saved immediately. This feature is independent of the selected storage procedure and can be helpful if there are negative voltages, high voltage fluctuations or ripple.

Press [ENTER] to complete the series of measurements.

If there was an error during measurement (e.g. the wrong cell of a storage battery was measured), you can repeat the measurement as often as you like by selecting the corresponding value and simply overwriting it. Press [←] or [→] to move to the beginning or end of the measurement, and press [↑] or [↓] to gradually move back and forth and then overwrite the wrong measurement by a new measurement.

Please note:

If you are at the end of a series of measurements and return to the start of the measurement by pressing the [←] or [↑] key (e.g. for checking the total voltage once again), you have to keep in mind that:

If the total voltage is not measured again, but confirmed by pressing [ENTER], the display of the cell number will change to the cell that will be measured next at the end of the series of measurements.

If the total voltage is measured again, the display of the cell number changes to cell 001. If you want to save the total series of measurements nonetheless, you have to jump to the end of the series of measurements by pressing the [→] or [↓] arrow keys in order to prevent that the series of measurements only consists of the total voltage measurement. The series of measurements will always be closed at the point where you selected the „Complete series of measurements“ menu.

If you want to measure the total voltage after a series of measurements is complete, you can also press the [F2] key. In this case, the AS pro will go back to the start of the series of measurements (and displays “BAT” in the upper left corner of the display). Now the total voltage can be measured, and immediately after this measurement has been taken, the AS pro jumps to the end of the series of measurements, which now can be continued or completed.

Here is another example of starting a series of measurements:

```
Start 001 Idle 20000
Ident No. Manual
Cyclic storage
↑↓↔ Clear Enter
```

[ENTER] will start a series of measurements having the sequential number 001. The identification number will be entered manually, and the selected storage procedure is „cyclic“. A remaining total of 20,000 measurements can be stored in the memory. Pressing [CLEAR] will return you to the previous menu item without starting a measurement.

Press [ENTER] to start a series of measurement consisting of cyclic measurements.

Symbol for cyclic measurement and (total) number of saved values.

Number of the current series of measurements

The measured value will be saved immediately after starting the series of measurements. Therefore the AS pro should already be connected to the voltage to be measured.


If you press [+], the current measurement will be saved immediately and independently of the time delta (delta-t).

Press [ENTER] to complete the series of measurements.

3.2.2 Special Feature for Recording Series of Measurements

During an single or cyclic series of measurements you can interrupt the recording process and power the AS pro off. When you power the AS pro on again, it resumes recording measurements at exactly the same point where it was interrupted.

3.2.3 Completing a Series of Measurements



By pressing [CLEAR] you return to the previous menu item.

Press [←] or [→] to toggle between the "with/without temperature input" default. Or press [↑] or [↓] to toggle between the "with/without density of acid" default.

If you have selected input without temperature and without density of acid, the series of measurements will be saved right away by pressing the [ENTER] key.

After pressing [↑] or [↓] to move to the third line, you can toggle between the „Save“ and „Cancel/Abort“ options. You can now completely cancel/abort the last series of measurements, when you press [ENTER] and confirm the displayed confirmation dialog.

If you have selected "with temperature" and "with acid" as defaults, you can now enter the temperature and the density of acid or an acid density range, (e.g. +27°C and 1.12-1.28 kg/l)

```

Save Test Series
Enter Temperature
[+27]
↑↓↔ Clear Enter
  
```

Confirm your input by pressing [ENTER]. Press [CLEAR] to return to the previous menu item.

```

Save Test Series
Enter Acid Density
[1.12-1.28]
↑↓↔ Clear Enter
  
```

Confirm your input by pressing [ENTER]. Press [CLEAR] to return to the previous menu item.

If you select Cancel/Abort, you will be prompted to confirm this option in order to prevent inadvertent deletion of a series of measurements.

```
Delete Test Series
Are you sure?
      Yes   No
      +   Enter
```

If you press the [+] key, the series of measurements will be **deleted and cannot be recovered**.

By pressing the [ENTER] key, you return to the current series of measurements.

3.3 Displaying and Printing Stored Series of Measurements

In the „Display and print measurement“ dialog, choose `View Test Series` from the menu which displays after confirming the **AS pro** voltmeter function by pressing [ENTER].

```
Start Data Logging
View Test Series
Delete Test Series
↑↓      Clear   Enter
```

The [↑] and [↓] arrow keys are used to select different features which subsequently are applied by pressing [ENTER]. Press [CLEAR] to return to the voltmeter function.

You have selected `View Test Series`. Press [ENTER] to confirm your selection and go to the menu for selecting a series of measurements. First of all, select the desired series of measurements which you want to display or print.

```
001 00060 Value
470011
13.03.08 11:35:51
↑↓↔   Clear   Enter
```

Series of measurements and number of measured values

Identification number of the storage battery or measurement

Date and (starting) time of

Press the [↑] or [↓] keys if you want to view an overview of the stored series of measurements. Press [↓] to move to next measurement, or press [↑] to return to the previous measurement.


Press the [←] arrow key to return to the start (i.e. the first series of measurements), or press the [→] key to move to the end (i.e. the last series of measurements).

Press [ENTER] to confirm the selected series of measurements.

Press [CLEAR] if you want to return to the previous menu item.

3.3.1 Displaying Series of Measurements

After you have selected a measurement by pressing [ENTER] you can choose the next menu item. Here you can decide how the measurement should be displayed or printed. A series of measurements can be displayed or printed with or without time information.



The [↑] and [↓] arrow keys are used to select different features which subsequently are confirmed by pressing [ENTER].

The [←] and [→] arrow keys are used for changing and applying the features of a selected function.

Press [CLEAR] to return to the previous menu item.

Press [ENTER] to confirm the selected series of measurements.

By pressing [↓] or [ENTER] you can move to the next page.

```

00001 12.34V 14:05:09
00002 12.33V 14:05:13
00003 12.32V 14:05:18
00004 12.35V 14:05:23
↑↓↔ Clear Enter
  
```

Use the [↑], [↓] or [ENTER] keys to view the stored measurements page by page. Press [↓] or [ENTER] to move to the next page, or press [↑] to return to the previous page.

If you press [←], you will see the first measurements. If you press [→], you can view the last measurements.

A series of measurements will be displayed in the following order:

„Number, voltage, time“

provided that this series of measurements was recorded by using the single storage method.

If you have selected the cyclic procedure when starting a series of measurement, the following order is used:

„Number, time, voltage“

If you have entered values for temperature and density of acid, you will find them at the end of the series of measurements.

```
001 00060 Value
Temperature:+27
Acid density: 1.12-1.23
↑↓↔ Clear Enter
```

If you want to return to the measurements menu containing the stored measurements, you have to press [CLEAR]. If you press [ENTER], the last values of the series of measurements will be displayed again.

If you measured the total voltage of a series of measurements, the total voltage will be displayed in the top line at the end of the series of measurements.

```
Battery voltage:247.8V
Temperature:+27
Acid density:1.12-1.23
↑↓↔ Clear Enter
```

3.3.2 Printing Series of Measurements

If you want to print a series of , select the `Print measurements` option already described above. Again, you can print this measurement with or without time.

```
001 00060 Value
Print stored Data
with Time and Date
↑↓↔ Clear Enter
```

The [↑] and [↓] arrow keys are used to select different features which subsequently are applied by pressing [ENTER]. If you press [CLEAR] you will return to the measurements menu containing the stored measurements.

Press [ENTER] to start transmitting the series of measurements to the infrared interface of the powered-on printer.

```
printing ...
Clear
```

Please ensure that there is a direct line-of-sight connection between the AS pro and the printer's infrared receiver in order to guarantee error-free data transmission. Make sure that the distance between the AS pro and the infrared receiver is not greater than 60 cm.

You can cancel the data transmission to the printer by pressing [CLEAR]. If the data transmission is complete, you will be returned to selection menu of the stored series of measurements.

By pressing [CLEAR] you return to the previous menu item.

Please note:

Please also read the printer's operating manual thoroughly.

3.3.3 Special Printing Features

When you print out series of measurements, you can also create a description text for the AS pro printer. This text will precede the series of measurements. The text can contain company information such as the company name, address, tester, customer, etc. that can be assigned to a measurement.

Please note that this text has to be created by a PC program and subsequently must be transmitted to the AS pro.

3.3.4 Printing Example

Customer:_____

Battery type:_____

No. of cells:_____

Operating since:_____

Checked during:

Charge.....	[]
Continuous charge	[]
Discharge.....	[]
No-load voltage	[]

Measurement:001

ID number: 1234

Battery voltage: 18.51V

Start 10.03.00 10:29:51

Cell....	voltage...	time
00001	2.31V	10:30:00
00002	2.32V	10:30:04
00003	2.30V	10:30:09
00004	2.33V	10:30:16
00005	2.32V	10:30:22
00006	2.30V	10:30:28
00007	2.31V	10:30:33
00008	2.32V	10:30:39

This example illustrates a header that helps the tester to manually add certain information in the field. The actual series of measurements starts with the sequential number, the identification number (ID number) and the starting time of the measurement. Subsequently all of the measured voltage values will be printed. If you do not want to print certain time information of individual measurements, disable that function in the corresponding menu.

3.4 Deleting Measurements

From the main menu choose `Delete` measurements. Select this menu from the menu which appears after pressing the [ENTER] key in the **AS pro** voltmeter function.

```
Start Data Logging
View Test Series
Delete Test Series
↑↓      Clear   Enter
```

The [↑] and [↓] arrow keys are used for selecting different features which subsequently are applied by pressing [ENTER]. Press [CLEAR] to return to the previous menu.

When you have pressed [ENTER] to select `Delete Test Series`, you will be prompted to confirm this option in order to prevent inadvertent deletion of all series of measurements.

```
Delete all !!!
Are you sure?
      Yes  No
      +   Enter
```


If you press the [+] key, all series of measurements will be irretrievably deleted and cannot be recovered.

By pressing [ENTER] you can return to the main menu **without** deleting the series of measurements.

3.5 Using the Battery Charger

3.5.1 State of Charge Display

A battery symbol on the AS pro's LCD illustrates the state of charge. It has a resolution of about 10%. Thus you can determine the AS pro's remaining operating time at any time (see specifications).



3.5.2 Charging Procedure

When the battery symbol signals an insufficient remaining operating time, you should recharge the accumulator of the device. Use the supplied battery charger for this purpose. At first connect the battery charger to the AS pro and then plug it into the mains socket.

Please note:

The AS pro must be powered off during charging so that the battery charger can recognize fully charged storage batteries.



Please let the battery charger load until the float charge mode is achieved. This is indicated by a **continuously flashing green LED**. Only then the “full” charge state will be taken over when powering the AS pro on.

These are the different states of charge:

- yellow LED: flashes - initializing (test phase)
- orange LED: flashes - quick charge
- green/yellow LED: blinks - recharge (storage batteries are not fully charged yet)
- green LED: flashes - float charge (storage battery is fully charged)

4 Troubleshooting

4.1 Voltage Measurement Problems

Error description	Possible cause	Measures to be taken
No measurement	No contact to the voltage to be measured	Use new measuring probes
No measurement	Defective measurement leads	Use new measurement leads
No measurement storage	Measurements have not been started	Select "Start Data Logging" in the AS pro menu
No measurement storage	Wrong storage method selected	Preselect <i>single</i> storage in the AS pro menu
No measurement storage	Wrong AS pro parameter settings for min. value, hysteresis, ripple	Transmit new settings to the AS pro
No measurement storage	Wrong AS pro parameter settings for manual button	Transmit new settings to the AS pro
No measurement storage	Ripple of the voltage to be measured is too high	Press the „+“ key for manual storage or change ripple setting
No cyclic storage of the measurement	Wrong storage method selected	Preselect <i>cyclic</i> storage in the AS pro menu
Wrong cycle time when storing voltages	Wrong AS pro parameter settings for delta-t time	Transmit new settings to the AS pro

4.2 Problems with the operating time/powering-on

Error description	Possible cause	Measures to be taken
Device cannot be powered on	Empty accumulators	Connect AS pro to the battery charger and charge until the full charge symbol appears
Device cannot be powered on	„Enter“ key was not pressed long enough	Press „Enter“ key for at least 1 second
No display on the LCD	Wrong contrast setting	Increase AS pro LCD contrast by pressing F4/F7 function keys
Operating time is too short	Defective accumulators	Have the AS pro repaired

4.3 Printing Problems

Error description	Possible cause	Measures to be taken
Measurements do not print	Printer is powered of (Power LED does not flash)	Power on the printer
Measurements do not print	Printer is offline (online LED does not flash)	Press online button
Measurements do not print	Printer ran out of paper	Insert new paper roll
Measurements do not print	Defective patch cord for infrared adapter and printer	Connect a new cable
Measurements do not print	Defective infrared adapter	Use PC to check infrared adapter and replace if defective
Measurements do not print	Defective printer power supply	Use new plug-in power supply (take care of polarity and voltage)
Measurements do not print	Empty printer accumulator	Connect printer to plug-in power supply and recharge (see printer manual for more details)
Faulty measurement printout	Optical distance between AS pro and printer is too high	Reduce distance between infrared adapter and AS pro

4.4 Problems with the infrared connection to the PC

Error description	Possible cause	Measures to be taken
No communication between AS pro and PC	No direct line-of-sight connection between AS pro and the PC's infrared adapter	Reduce distance between infrared adapter and AS pro (refer to specifications)
No communication between AS pro and PC	No direct line-of-sight connection between AS pro and the PC's infrared adapter	Align infrared adapter and AS pro
No communication between AS pro and PC	Wrong COM port preselected in the software	Select the correct COM port to which the infrared adapter connects
Communication errors between AS pro and PC	Optical distance between AS pro and PC is too high	Reduce distance between infrared adapter and AS pro
Communication errors between AS pro and PC	Defective infrared adapter	Use PC to check infrared adapter and replace if defective
Communication errors between AS pro and PC	A series of measurements is active in the AS pro	Complete and close the series of measurements
No measurement storage	A series of measurements is active in the AS pro	Complete and close the series of measurements

4.5 Troubleshooting problems when reading RFID transponder data

Error description	Possible cause	Measures to be taken
No communication between AS pro and RFID transponder	Distance between AS pro and RFID transponder is too long	Reduce the distance between RFID transponder and AS pro (see specifications)
No communication between AS pro and RFID transponder	Wrong RFID transponder type selected	Use the F6 key or PC software to select the correct type
No communication between AS pro and RFID transponder	RFID transponder is defect	Try a new or another RFID transponder
No communication between AS pro and RFID transponder	RFID transponder is attached to aluminum (or another inadequate material)	Attach the RFID transponder to another material

5 Maintenance

5.1 Cleaning

For cleaning the AS pro, moisten a soft cloth with lukewarm water, carefully wipe the AS pro and rub it dry with a clean cloth. Do not use any solvents or aggressive detergents, since they may damage the surface of the casing. Wipe the LCD with a soft cloth to prevent the display from getting scratched.

A soft and dry anti-static cloth is sufficient for cleaning slight soiling.

5.2 Maintenance

The AS pro operates almost maintenance free. To maintain the accumulators' durability, do not store the AS pro in a discharged state for a longer period of time.

Periodically submit the device for calibration to ensure that the specifications will be maintained (see specifications for calibration intervals).

Ensure that the AS pro and all of its accessories are in a perfect condition before commissioning and using them. Do not use the device if you notice signs of damage on casing, connectors and cables.

Also read the "Safety Information" chapter thoroughly before using this device.

6 Accessories and replacement parts

6.1 Accessories

Article number	Designation
00963-0600.00	Thermal printer for the AS pro, including power supply/battery charger, battery pack, paper roll, patch cord for infrared transmitter, infrared transmitter
00963-0406.00	Headphone with patch cord for the AS pro
00963-0408.00	Beep Transmitter 85db(A)-1m for AS pro
00963-0410.00	RFID Transponder 50mm Unique round
00963-0410.01	RFID Transponder ISO Smart Card Hitag1
00963-0410.02	RFID Transponder ISO Smart Card Hitag2
00963-0500.02	Windows Toolkit Software CD V2.x for AS pro
00963-0500.05	Windows Toolkit Software CD Update for AS pro
00963-0501.00	Infrared transmitter for AS pro / thermal printer
00963-0502.00	Adapter 9/25pol. AS pro Infrared transmitter
00963-0700.00	Windows Data processing Software CD V2.x for AS pro
00963-0700.05	Windows Data processing Software CD Update for AS pro
00963-0800.00	Handheld Density Meter DMA 35n
00963-0800.01	Handheld Density Meter DMA 35n Ex
00963-0801.00	RS232/IR-patch cord for DMA 35n
00963-0802.00	Transport case for DMA 35n
00963-0805.00	RFID Transponder Reader and Programmer USB

6.2 Replacement parts

Article number	Designation
00963-0401.00	Foam-padded AS pro case
00963-0402.01	AS pro battery charger
00963-0403.00	Set of red and black measurement leads (1.5 m long)
00963-0403.01	Set of red and black measurement leads (2.0 m long)
00963-0403.02	Set of red and black measurement leads (1.5 m long) with button
00963-0404.00	Patch cord with 3.5 mm jack for AS pro headphone
00963-0405.03A	English AS pro Operating Instructions
00963-0601.00	AS pro thermal printer
00963-0602.00	Power supply/battery charger for the AS pro thermal printer
00963-0603.00	Patch cord for infrared transmitter of AS pro thermal printer
00963-0604.00	Battery pack for the AS pro thermal printer
00963-0605.00	Paper roll for the AS pro thermal printer

